

Accord¹⁵

Correcting Damaged Multi Clips

Installation & Maintenance

SBC-R Center Track Section Repair Kit
Includes Multi Clip, Set Screw, and Mounting Tape.
Attachment screws not included.

The molded plastic Multi Clips may become damaged if SignBands are forced into position when improperly aligned or improperly removed.

Given sufficient space on larger assemblies, it is possible to add additional Multi Clips alongside damaged or broken strips in lieu of removing and replacing the damaged Multi Clip(s).

Ordering Parts: Multi Clip track repair sections (SBC-R) are available in 90mm lengths and include the plastic Multi Clip. Double-sided adhesive tape is included, along with holes for mechanical fastening, depending upon the mounting surface.

1. Remove SignBands necessary to access damaged MultiClip(s). There must be at least a 90mm opening between bands in which to insert the Center Track Section Repair Kit.
2. Snap SignBand onto replacement Center Track Section and position SBC-R a minimum of 4" from end of SignBand. Note: Future removal of SignBand will be hampered unless adequate space is provided between Side Track and SBC-R.
3. Peel protective liner from double-sided tape.
4. Replace Sign Band and Center Track Section, pressing firmly over tape area.

